



VAISA	LA			Orderer				Orc	Jer n	umbe	r
ocument code: alid from:	DOC231605 2018 June 8th										
WD - Vis	sibility Sensors and Pr	esent Weather Dete	ctors								
	-			P	WD					N	PRIC
ensor Type	PWD10	Visibility Sensor	MOR Range to 2km		A						
	PWD20 PWD50	Visibility Sensor Visibility Sensor	MOR Range to 20k MOR Range to 50k		BR						
	PWD30 PWD20W	Visibility Sensor	Wind Turbine Versi								
	PWD12	Present Weather Detector	MOR Range to 2km		c						
	PWD22	Present Weather Detector	MOR Range to 20k		D						
	PWD52	Present Weather Detector	MOR Range to 50k		S						
	PWD22M	Present Weather Detector	For TACMET syste		E F						
onnection Cable	PWD22MS	Present Weather Detector No cable	Green Model with S	tandard Interfaces	F N						
	217150	Mast Cable 3.85 m			3						
	217147	Mast Cable 8 m			1						
	241767	Mast Cable 10 m			6						
	217148 217149	Mast Cable 15 m			4						
ood Heaters and Te		Mast Cable 35 m No Hood Heaters, Standard Temp	erature Measurement		5 N						
		Hood Heaters for Freezing Condition		re Sensor in Cross Arm.	н						
		Hood Heaters for Freezing Condition	ns. Temperature Sensol	in External Radiation	т						
- Aliaba Cuitab		Shield (mounting to standard cros None	s-arm or pole mast of a	ameter 60100mm)	N						
ay/Night Switch	PWL111	Background Luminance Sensor									
pplication Specific		None			-	N					
Add-ons	ASM212451	Maritime insulator (for e.g. shipdeck	installations)			1					
pecial Settings		None ROSA Configuration				N 1					
		ROSA Configuration AWS520 Configuration				1					
		US AWOS Configuration				3					
		PWD22 AviCast Configuration				5					
		AviMet Configuration PWD20W Configuration, RM = 1, Al	1 10000 410 50	0		7					
		(minus sign in relay alarm limits in				А					
		PWD20W Configuration, RM = 1, Al				_					
		(minus sign in relay alarm limits in				в					
		Special Settings (Define):				х					
Interface Unit	BOX221	None 24V DC Power Supply (115VAC2	BOVAC)			N 1					
	BOX222 (230V)	24V DC and AC Power Supply (230		d Heaters		2					
	BOX222 (115V)	24V DC and AC Power Supply (115				6					
	BOX222W-230	24V DC and AC Power Supply (230				W					
Data Interface	BOX222W-115	24V DC and AC Power Supply (115	VAC) with Transient Pro	tection and Relays		Х	1 <u>, </u>				
ata interiace	ISOLATEDRS485	Standard RS-232 and RS-485 Isolated RS-485					A B				
	LEASEDLINEMODEM	Modem DXL421 for 2-wire V.21/V.2	2				c				
	4WIRELINEMODEM	Modem DXL421 for 4-wire V.23					D				
last		No mast					N				
	DKP203W PWFM210	Aluminum Pole Mast, 3m, dia. 60 m. Glass Fiber Pole Mast, 2.1 m, dia. 6					2				
tandard		Standard Clamp for Mounting the		(for Sensor Mounting Only)				N			
tainless Steel	APPKP60-SET1/2 + MAST60-SET	Mounting Clamps for dia. 60 mm Po			1)			A			
lounting	APPKP75-SET1/2 + MAST75-SET	Mounting Clamps for dia. 75 mm Po						в			
Accessories	APPKP100-SET1/2 + MAST100-SET	Mounting Clamps for dia. 100 mm P						C			
	APPKP60-SET1/2 + MAST86-SET APPKP60-SET	Mounting Clamps for dia. 60/86mm Mounting Clamp for dia. 60 mm Alur			Jnit BOX22X Mounting)			D E			
	APPKP75-SET	Mounting Clamp for dia. 75 mm Pole						F			
	APPKP100-SET	Mounting Clamp for dia. 100 mm Po						G			
tainless Steel	228801	Rugged Mounting Clamp for dia. 40						1			
ugged Mounting	228802	Rugged Mounting Clamp for dia. 50						2			
ccessories or High Wind	228803 228804	Rugged Mounting Clamp for dia. 60 Rugged Mounting Clamp for dia. 75			9)			3 4			
or High wind oads and Heavy	228804 228805	Rugged Mounting Clamp for dia. 75 Rugged Mounting Clamp for dia. 10						5			
lechanical	228803 + MAST60-SET	Rugged Mounting Clamps for dia. 60			Nounting)			6			
tress	228804 + MAST75-SET	Rugged Mounting Clamps for dia. 75	5 mm Pole Mast (for Se	nsor and Interface Unit BOX22X	Mounting)			7			
	228805 + MAST100-SET	Rugged Mounting Clamps for dia. 100 mm Pole Mast (for Sensor and Interface Unit BOX22X Mounting) 8									
alibration Tools	228803 + MAST86-SET	Rugged Mounting Clamps for dia. 60 None	voomm vaisala Glass F	iver rule wast (for Sensor and In	nerrace Unit BOX22X Mo	uriung)		9 N			
	PWA12	Calibrator Set for two-point calibration	on check					с			
	PWA13	Calibrator Set for three-point calibra						D	.		
laintenance Cable		No cable						_	Ν		
ser's Guide	QMZ101	RS Cable for BOX221, BOX222 and No User's Guide	HUSA						2	.	
		No User's Guide User's Guide	PWD10/20/50	English						A	
		User's Guide	PWD12	English					E	3	
		User's Guide	PW D22/52	English							
		Bedienungsanleitung	PWD10/20/50	German						2	
		Bedienungsanleitung Bedienungsanleitung	PWD12 PWD22/52	German German						5	
		Bedienungsanleitung Guide utilisateur	PW D22/52 PW D22/52	French						=	
		User's Guide	PWD10/20/50	Japanese							
		User's Guide	PWD12	Japanese						<	
		User's Guide	PW D22/52	Japanese						-	
		User's Guide	PWD10/20/50 PWD22/52	Chinese							
		User's Guide User's Guide	PW D22/52 PW D22/52	Chinese Russian						3	
		User's Guide	PWD12	Russian						r	
		User's Guide	PWD10/20/50	Russian						J	
					-					N	
eserved line]									-	OTAL	

Selections in bold are included in the prices of the basic versions. Selections in italic are available at an extra price.

 Example of order code with typical settings (PWD12 Sensor only):

 PWD
 C
 1
 N
 N
 N
 A
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N
 N

 Example of order code (PWD22 Sensor in standalone configuration):

 PWD D
 1
 H
 N
 N
 2
 A
 3
 D
 C
 2
 C
 N

End customer: