




WIRING DIAGRAM

CTC LPT202 AND LPT302 LOOP POWER TRIAXIAL SENSORS



Pin A Axis X


Pin B Axis X Common

Pin C Axis Y

Pin D Axis Y Common

Pin E Axis Z

Pin F Axis Z Common



MEASUREMENT
CHANNEL 1
(mVAc/g)
IEPE SUPPLY
Axis X

MEASUREMENT
CHANNEL 2
(mVAc/g)
IEPE SUPPLY
Axis Y

MEASUREMENT
CHANNEL 3
(mVAc/g)
IEPE SUPPLY
Axis Z